

Number: BA 06/11	Date: 01.06.11	Circulation:	5	KEY: 1 = Customer Service/ Technical Support 2 = Field Sales 3 = Inter-company 4 = External Distributors 5 = Special Circulation
Subject: Flite Cylinder Hose - CYL – FLITE – 10/15/SL - Update				

Following notification from a customer of an incident involving a hose detachment on a Sabre Flite unit, Scott Safety would like to recommend the following inspection activities.


Customers can perform a basic inspection of the ferrules at each end of the hose, making sure that the hose can be seen through the inspection hole, the ferrule is not loose and when pressurised there is no leak. If you have any concerns having made these checks, please remove the set from operation and contact your Scott representative.

The photos below show in detail the parts concerned.

Photo 1 – Ferrule



Photo 2 – Inspection pit.



We do not expect customers to encounter problems with the equipment provided recommended user instructions are followed.

If you have any concerns please contact your Scott Safety representative.

Rob Evans
Quality & EHS Manager